Appendix A Black Lion Road Petition CMT Report May 2023

Accident Report



Accident Details

A042319	Wednesday BLACK LION ROAD 301 254 LAMP	Veh 1	Car	Going ahead	NW to S	E			
R1: C 2060	22/05/2019 POST N/A CAPEL HENDRE	Veh 2	Car	Stopping	NW to S	E FSF	F	05	Slight
	1630hrs (N/A)	Veh 2	Car	Stopping	NW to S	E RSI	M	12	Slight
	Daylight:street lights present	Veh 2	Car	Stopping	NW to S	E Dri	F	32	Slight
E 258,671	Dry	Veh 3	Car	Wait go ahead held	NWto S	E Dri	F	36	Slight
N 211,997	Fine without high winds								
	30 mph								

Participant: Confidence: Causation Factor: Failed to judge other persons path or speed Vehicle 001 Very Likely Failed to look properly Vehicle 001 Possible

ALL THREE VEH'S TRAV ON BLACK LION ROAD FROM CROSS HANDS TO CAPEL HENDRE. V3 WAS ON STOP DUE TO TRAFFIC AHEAD, SO WAS V2. V1 TRAV BEHIND STARTED TO BRAKE & NOT STOPPED IN TIME & DRIVEN INTO BACK OF V2 SHUNTING IT INTO REAR OF V3. NO SKID MARKS ON ROAD &

CONDITIONS WERE GOOD. V1 & V2 - ALL THREE OCCUPIERS SUFFERED WHIPLASH. YOUNG BOY HAD TWO BLACK EYES. V3 -WHIPLASH. (CASUALTIES - SEATBELT WORN BUT NOT INDEPENDENTLY CONFIRMED)

NW to SE Dri A022120 Monday BLACK LION ROAD TY-A-FI Veh 1 Car Going ahead F 80 Slight 16/03/2020 N/A CROSS HANDS (N/A) Veh 2 Car Parked 0 to 0 Ped M 52 Slight R1: C 2060 1220hrs Daylight:street lights present

E 257,462 Dry

Fine without high winds N 213,036

30 mph

Participant: Confidence: Causation Factor: Uncorrected, defective eyesight Vehicle 001 Possible

> V2 PARKED ON SIDE OF ROAD. V2 DRIVER WAS ON PAVEMENT & LOADING SACK OF GARDEN WASTE ONTO V2'S TRAILER. DRIVER V1 FAILED TO SEE V2'S TRAILER & COLLIDED WITH IT. TRAILER MOVED FORWARD & WENT OVER V2 DRIVER'S FOOT. (CASUALTY 1 - SEATBELT WORN & INDEPENDENTL

Y CONFIRMED)

SE to NE Dri M 45 Slight A091122 Wednesday Black Lion Road junction New By-Pass Veh 1 Car Turning right

> 02/11/2022 Road Veh 2 Car NE to SW Going ahead

R1: U 1720hrs

Darkness: street lights present a R2: A 476

E 257,607 Wet/Damp

N 212,899 Raining with high winds

30 mph

Participant: Confidence: Causation Factor: Failed to look properly Vehicle 1 Very Likely

> V2 trav along New Link Road to Cross Hands & V1 trav along Black Lion Road from Capel Hendre. When at jct with new By-Pass road, V1 pulled out, turned right & V1 & V2 collided.