

## Appendix 5

Llandeilo AQMA

Llandeilo AQMA & Action Planning - NO2 Passive Tube Result Calendar Year 2017 Annual Mean

Site	Site Ref	Nitrogen Dioxide levels (ugm-3)												Raw Data					
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec	Count Blank	Count +	Annual Mean	Adj fact	Data Post Bias	Over 40ug/m3
North roundabout (No 8 Rhosmaen Street (North)	FA/01	32.3	24.1	20.4	15.3	16.7	15.7	13.4	14.7	17.6	19.6	27.7	17.9	0	12	19.62	0.77	15.10	FALSE
Rhosmaen Street (No 69)	DA/15	47.0	34.2	35.9	29.1	31.4	25.9	24.3	24.0	27.4	33.1	47.2	33.4	0	12	32.74	0.77	25.21	FALSE
Rhosmaen Street (No 87)	DA/03	48.4	38.4	35.9	26.2	26.3	24.3	25.0	24.1	27.2	30.7	44.5	25.7	0	12	31.39	0.77	24.17	FALSE
Rhosmaen Street (No 87)	DA/03	46.3	37.6	39.5	28.0		25.9	24.0	24.6	28.1	33.7	41.8	30.5	1	11	32.73	0.77	25.20	FALSE
Llandeilo - Rhosmaen Street	Carm/013	56.5	48.7	51.5	38.5	24.9	39.1	35.1	34.7	41.7	49.3	61.2	44.1	0	12	43.78	0.77	33.71	FALSE
Rhosmaen Street (Evans Butchers)	DA/05A	58.8	52.2	49.8	32.3	31.9	34.8	35.5	35.9	37.8	39.1	57.5	43.6	0	12	42.43	0.77	32.67	FALSE
Rhosmaen Street (Evans Butchers)	DA/05B	61.7	52.8	53.2	36.3	46.3	39.6	38.1	38.5	42.4	46.3	55.4	42.4	0	12	46.08	0.77	35.48	FALSE
Rhosmaen Street (Evans Butchers)	DA/05C	63.6	54.9	51.7	41.3	45.0	37.0	35.0	34.8	41.3	45.7	58.6	45.6	0	12	46.21	0.77	35.58	FALSE
Rhosmaen Street (Castle Hotel)	DA/07	66.5	62.0	57.2	47.6	46.5	43.5	39.9	37.3	44.4	46.4	66.9	44.2	0	12	50.20	0.77	38.65	FALSE
Llandeilo - Rhosmaen Street (2)	Carm/083	72.0	63.6	49.3	43.4	46.5	37.9	40.1	41.5	47.5	51.6	73.2	48.3	0	12	51.24	0.77	39.46	FALSE
Rhosmaen Street (No 123)	DA/09	77.4	59.8	61.8	36.6	57.0	40.5	44.7	46.1	47.2	53.4	77.0	53.4	0	12	54.58	0.77	42.02	OVER
Rhosmaen Street (No 133)(Craft Shop)	DA/10	70.0	55.4	60.2	44.8	49.8	37.9	36.5	38.2	47.0	48.4	65.9	51.7	0	12	50.48	0.77	38.87	FALSE
Rhosmaen Street (No 74)(Style)	DA/11	62.4	50.6	56.2	48.8	42.8	42.0	42.6	41.9	41.3	51.5	70.1	47.6	0	12	49.82	0.77	38.36	FALSE
Stryd Y Brenin (Travel House)	DA/12	44.6	68.6	45.0	26.8		24.3	22.1	24.5	26.1	46.8	64.1		2	10	39.29	0.77	30.25	FALSE
Rhosmaen Street (Park Area)	DA/13	60.9	54.7	51.3	44.0	32.5	46.1	38.2	27.8	44.3	32.7	60.3	49.5	0	12	45.19	0.77	34.80	FALSE
Rhosmaen Street (Bin post by Bus stop)	DA/14	47.7	34.9	32.8	24.7	26.2	23.8	21.5	23.5	31.3	31.5		29.8	1	11	29.79	0.77	22.94	FALSE
Bridge Street (South)	DA/16	51.1	46.6	44.7	47.1	35.6	37.7	35.3	34.9	41.0	45.5	63.9	37.5	0	12	43.41	0.77	33.42	FALSE
South roundabout (No 40 Towy Terrace)	FA/03	34.5	27.8	28.2	22.7	21.1	18.2	18.1	17.6	20.2	24.8	36.9	26.9	0	12	24.75	0.77	19.06	FALSE
Heol Bethlehem (Opp School)	FA/07	19.3	14.6	12.2	9.9	9.0	7.4	7.2	6.8	9.6	10.6	16.3	11.6	0	12	11.21	0.77	8.63	FALSE
10 Heol Myrddin, Ffairfach	FA/06	35.1		25.6	22.9	20.6	13.7	15.7	16.5	18.5		30.6	23.1	2	10	22.23	0.77	17.12	FALSE
Ffairfach Chapel	FA/04	27.9	25.1	21.5	15.0	13.1	18.4	12.3	12.2	16.4	18.8	23.1	18.3	0	12	18.51	0.77	14.25	FALSE
Cennen Road (No 43)(Old Creamery)	FA/05	32.7	26.0	23.2	14.8	16.6	16.3	14.6	15.2	17.8	22.5	27.5	18.7	0	12	20.49	0.77	15.78	FALSE
Evans Butcher (Average) (WAQF)	DA/05	61.4	53.3	51.6	36.6	41.1	37.1	36.2	36.4	40.5	43.7	57.2	43.9	0	12	44.92	0.77	34.59	FALSE

- Tube Missing
- Tube found on ground
- Flower basket above tube
- Roadworks/traffic lights
- Broken Tube / cap
- Foreign object in tube
- Tube site not yet set up



Rhosmaen Street traffic orders

